5/22

DART AEROSPACE LTD	Work Order:	J3158
Description: Bearpaw Kit (48" x 19") 205/430	Part Number:	K10015
- TF05.06.02		10 -
<b>Dwg</b> : D2521 Rev. ► <b>I</b>	Qty:	() Kits
Ref: K10015 Rev. A; DSK086-6 Rev. A		Page 1 of 1

Step	Location	Procedure	Ву	Date	Qty
1	DC .	Issue Traveler	<del> </del>		
		Note: (1) K10015 Kit consists of Qty (2) D2521	S	05/05/09	سردر
		Dwg not required	A.	25/05/04	
2	DC	Photocopy bluefile: K10015			
	-	D205-564-011	1 .	,	1
-		D430-688-011	TH	65.06.03	20
1		and create labels per PPP K10015 CHG002 (Bag Bluefiles separately)	יוען	05.001	_
		(Bag Bluefiles separately) いんひ が	<u> </u>		
3	GA	Cut 2 blanks per (1) K10015 Kit	1		
		Cut blank: 19.50" x 48.00" x 1.00", thick (+0.030/-0.000) per			
	,	DSK086-6 Material: Black UHMW 1"			
		(MUHMWB10) Batch: 117726	20	- Al -11	٠,
4	MV	Inspect material for defects or damage prior to machining	חנו	05.0604	10
1 7	, ,	inspect material for defects of damage prior to machining	ZV	05.06.04	10
5	MV ·	Machine as per Folio FA222 and Dwg D2521		03.08.07	,,,
		Identify as D2521	12	05.06.04	10
6	QC2	Inspect parts as they come off the CNC machine	-	1 :	
			20	05.06.04	110
7	M∨	Deburr	1		
	5.43.7		717	08,06,04	10
-8	<del>-MV</del>	Form as per Dwg D2521 using bending Jig DT8328	<del> </del>		<del></del> .
9	QC8 & 5	Second inspection '	ļ,		-
	QC0 & 3	Second inspection	John John	05/06/08	16
10	KP	Pick: Packing Kit (Note: D2521 is on the BOM as material	· · ·	03106100	10
		from step 3)			
		Qty Part Number Description Batch			
		8 D2182B055 Rubber Cushion B21 87)			
		16 D2274 Radius Block B2 \$ 17 4			
		2 D2521 Bearpaw B23/58			
		16 D2529 Washer B22 504			.
		8 D2947 Clamp B21588			
		16 AN4-15A Bolt <u>M14067</u>	1		
		16 AN960JD416 Washer MIG941	ĺ		
1		16 MS21042L4 Nut (or -4) M15924			
		Paperwork package from Step 2	W	articles.	_ \
11	004		^	05/04/20	10
. 11	QC4	Inspect Kit for 100% Completeness on the W/O	CZ		
12	PK	Identify and pack for shipping as per PPP K10015	201	05/06/20	10
,		Rev.D	C7	05/06/20	10
13	AC			/ /	
		Cost / part 6440	Ali	05/06/22	10
14	DC .	Close W/O (6.82) Inspect Level 21	IN		
1		Inspect Level 21	4X	05,06.27	10

Rev	Date	Change	Revised By	Approved
Α	01.10.16	K10015 created for Bearpaw Kit (MPP 2164)	SM	
В	03.05.26	Reformat; Incorporated D2521	KJ/RF	
С	04.02.17	Tolerance added to Step 3	KJ/JLM	-#-

RELEASE 1 04.52.20 F

## **Dart Aerospace Ltd**

W/O:		WORK ORDER CHANGES											
DATE	STEP	PROCEDURE CHANGE By	Ву	Date	Qty	Approval Mfg / Design Mgr	Approval QC Inspector						
		<b>?</b>											
		•		•	<u> </u>								
		*											

NCR:		WORK ORDER NON-CONFORMANCE (NCR)										
:- ·		Description of NC		Corrective Action Section B	Verification	Approval	Approval					
DATE	STEP	Description of NC Section A		Action Description Sign & Date	Section C	Approval Design Mgr	Approval QC Inspector					
	,	· · · · · · · · · · · · · · · · · · ·										
						-						
	ļ	100000000000000000000000000000000000000										
				•								

Part No:	PAR #:	Fault Category:	NCR:	Yes No	DQA:	Date:
NOTE: Date & initial all entries				QA: N/C C	losed:	Date:

DART AEROSPACE LTD	Work Order:	03158
Description: Bearpaw	Part Number:	D2521
Inspection Dwg: D2521 Rev: H		Page 1 of 1

## FIRST ARTICLE INSPECTION CHECKLIST

X First Article Prototype

	pection Sheet ving Dimension			Accept	Reject	Method of Inspection	Comments		
Α	1.000	+/-0.030	1.003						
В	5.600	+/-0.030	5.596		1,				
С	11.500	+/-0.030	11,500						
D	10.250	+/-0.010	10,250	/	-				
E	13.250	+/-0.010 /	13,250						
F	8.500	+/-0.010/	8.500	/					
G	22.125	+/-0.030	22./25	/					
Н	8.75	+/-0.010	8.750	<u> </u>					
ı	44.500	+/-0.030	44,500						
J	6.688	+/-0.030	4.688	/					
K	5.625	+/-0.030	5.624						
L	7.000	+/-0.030	7.000						
М	5.000	+/-0.010	°5,000						
Ν	4.000	+/-0.030	3,996						
0	6.625	+/-0.030	6.625			!	. 72		
Œ.	19.000	+/-0.030	19,000				· · · · · · · · · · · · · · · · · · ·		
Q	0.31 x 45°	+/-0.030	, 3/X45°						
R	0.19 x 45°	+/-0.030	-19 x45°	/			Took out		
S	0.50 x 45°	+/-0.030	,50 × 45°	/					
Т	0.38 x 45°	+/-0.030	.38 X 45"	/					
J	0.063 x 45°	+0.030/-0.010	.010 245'	/					
V	Ø0.260	+0.005/-0.000	9,260				4.2		
W	Ø0.93	+/-0.030	, 929				, N		
X	0.30	+0.030/-0.010	,301						
Υ	0.375	+/-0.010	175.	-					
Z	0.750	+/-0.030	.765						
AA	. 0.250	+/-0.010	.260						
AB	4.000	+/-0.030	4000			······································			
AC	6.625	+/-0.030	6.675				Ç2,s		
- AD	0.950	+0.030/-0.010	,937				Na.		
AE	0.375	+/-0.010	3 397						
AF	3.399	+/-0.030	3.399	/					
AG	6.625	+/-0.030	6.1625	./					

Measured by:	. 42	Audited by:	R	Prototype Approval:	N/A
Date:	PO.00.00	Date:	05-06.06	Date:	NIA


Rev	Date	Change		Revised by	Approved
Α	03.09.22	New Issue	· P/0 K10015	KJ/RF	4
				<del></del>	

RELEASED





DESIGN	DRAWN BY	DART AEROSPACE hawkesbury, ontario, cana	
CHECKED	APPROVED	DRAWING NO.	REV. H
#	#	D2521	SHEET 2 OF 2
DATE		TITLE	SCALE
03.01.30	,	205 BEARPAW	1:4



## Job Costing Report

Dart Aerospace Ltd. Hawkesbury

May 06, 2005 09:55 am

Work Order No : 0023158 : K10015 Project Name

: WK522 Project For : Main Work Order Type

Main WO Number : House Part Number: \*K10015

Description : Bearpaw Kit Manufactured : Yes

Amount Req'd: Amount Done :

Start Date : 05-04-05 Est Finish Date : 05-31-05

Act Finish Date : Drawings Reqd : No Ok for Approval :

Approval Rec'd :

Department Code:

Burden Flags : NNNNNNN WO Status : Open

Invoice State : Not Invoiced

Invoice Date : Invoice Number :

Invoice Amount: 0.00

Order Entry No :

OE Value :

Est Mark Up : 0.000% Actual Mark Up : 0.000%

\$0 Posted to Finished Goods

•		Estimated	Actual	Var. %	Posted	To Post
Material Cost	:	0.00	0.00	0.00	0.00	0.00
Engineering Hours	:	0.00	0.00	0.00		
Engineering Cost	:	0.00	0.00	0.00	0.00	0.00
Production Hours	:	0.00	0.00	0.00		
Production Cost	:	0.00	0.00	0.00	0.00	0.00
Packaging Hours	:	0.00	0.00	0.00		•
Packaging Cost	:	0.00	0.00	0.00	0.00	0.00
OverHead Hours	:	0.00	0.00	0.00		
OverHead Cost	:	0.00	0.00	0.00	0.00	0.00
CNC Hours	:	0.00	0.00	0.00		
CNC	:	0.00	0.00	0.00	0.00	0.00
Misc. Hours	:	0.00	0.00	0.00	•	
Misc.	:	0.00	0.00	0.00	0.00	0.00
•		========	========	======	•	
Burden	:	0.00	0.00	0.00		•
		========	========	======		
Total Cost	:	0.00	0.00	0.00		· ,
Mark up	:	0.000	0.000			
Selling Cost	:	0.00	0.00			

Actual Labour Hrs/Amount Done : Estimated 0.00 0.00 Profits/(Loss) 0.00 0.00